



SZ-T77

Instruction Manual





INTRODUCTION

The SZ-T77 is aesthetically superior version of their predecessors. A number of parameters are displayed alphanumerically to set the indicator for specific application.

This indicator can be used as Temperature, Humidity and Pressure indicator with below measuring range:-

Temperature Range:

For Parameter	-50.0°C to 99.0°C
For Display	-50.0°C to 100 °C / -58°F to 212 °F

Humidity Range:
SZ-HS-220:

For Parameter	30.0% to 90.0%
For Display	30.0% to 90.0%

SZ-HS-100/4-20mA:

For Parameter	0.0% to 99.0%
For Display	0.0% to 100%

4-20mA Settable Pressure range with Max. allowable as below:

For Parameter	-15 PSI to 600 PSI
For Display	-15 PSI to 600 PSI

CAUTION

WIRING: The probe and its corresponding wires should never be installed in a conduit next to control or power supply lines. The electrical wiring should be done as shown in the diagram. The power supply circuit should be connected to a protection switch. The terminals admit wires of upto 2.5sq mm.

WARNING: Improper wiring may cause irreparable damage and personal injury. Kindly ensure that wiring is done by qualified personnel only.

Maintenance: Cleaning: Clean the surface of the controller with a soft moist cloth. Do not use abrasive detergents, petrol, alcohol or solvents.


Notice: The information in this document is subject to change in order to improve reliability, design or function without prior notice and does not represent a commitment on the part of the company. In no event will the company be liable for direct, indirect, special, incidental, or consequential damage arising out of the use or inability to use the product or documentation, even if advised of the possibility of such damages. No part of this manual may be reproduced or transmitted in any form or by any means without the prior written permission of the company.

Controller: Controller should be installed in a place protected by vibration, water and corrosive gasses and where ambient temperature does not exceed the values specified in the technical data.


Probe: To give a correct reading, the probe must be installed in a place protected from thermal influences, which may affect the temperature to be controlled.

INSTALLATION

(1) Locate & tear out the template of the box (2) Drill through the template (3) Bring required wires between the drilled holes (4) Connect with caution as per wiring diagram on SZ-T77 back cover (5) Holding SZ-T77 at a slight angle, Locate the center of the connector and push into place till a snap action is felt.



SUGGESTED WIRING (230VAC)



1 3 4 5 6 7 8

Supply
230VAC, 50-60Hz

PE

GND

PROBE

4 - 20mA

A

KEYS ↓

SET / PRG

• PROBE: NTC (SZ-T75)

• “ * ”RH Sensor : SZ-HS-100/SZ-HS-220

• RH & Pressure Sensor: 4 - 20mA Input

TECHNICAL DATA

Housing : **Back housing** : Black ABS Plastic, Auto-extinguish
Connector housing : Polycarbonate Plastic V0 Grade

Front Cover : Polycarbonate Plastic V0 Grade

Dimensions : **Front:** 79 x 130 mm
Depth: 51 mm

Mounting : Wall mounting

Connections : Screw terminal blocks. < 2.5sq mm terminal only.

FR Grade : YES

Display : 3 X 2 inches 7 segment display & 7 LEDs for Indication

Data storage : Flash APROM Memory

Power input : 230 Vac ±10%, 50-60Hz Standard.

Operating temp. : 0°C to 60°C (non-condensing)

Operating humidity : 20% to 85% (non-condensing)

Storage temp : -25.0°C to 60.0°C (non-condensing)

Measuring Range : -50.0°C to 100°C / -58°F to 212°F (for Temperature)
30.0% to 90.0% (SZ-HS-220)
0.0% to 100% (SZ-HS-100/4-20mA)
Settable Pressure range with Max. allowable from-15 PSI to 600 PSI (4-20mA)

Input : **Temperature Sensor**
NTC probe, SZ-T75
RH Sensor (Selectable)
SZ-HS-100
SZ-HS-220
4-20mA Input
Pressure Sensor
4-20mA Input

Temp. Resolution : 0.1°C / 1°C / 1°F

Temp. Accuracy : +/- 1°C / 1°F

RH Resolution : 0.1% / 1%

RH Accuracy : +/- 5% (for SZ-HS-220)
+/- 3% (for SZ-HS-100/ 4-20mA input)

Pressure Resolution : 1 PSI

Pressure Accuracy : +/- 3 PSI

USER INTERFACE

Program mode:
Press for 2 seconds to enter in Program mode.

To set and save parameters in Program Mode.

In Min./Max. Log mode:
Press for 2 seconds to reset the min./max. Log of Temperature, Humidity and Pressure sensor.

Sensor display mode:
Press for 1 second to show the Temperature, Humidity and Pressure one by one with the time set in *tnd* parameter except default display. If any High / Low temperature, Humidity or Pressure fault is present then it will flash at the rate of 500ms with respective sensor value.

Min./Max. Log mode:
Press for 4 seconds to enter in Min./Max. Log mode. If this key pressed continuously for 4 seconds, indicator initially enter into Sensor display mode and after 4 seconds it will enter in Min./Max. Log mode.



In program mode:
Scroll through parameters and its values.

INDEX

Sr. No.	Para.	Description
1	<i>ntC</i>	Temperature probe and Unit selection
2	<i>rSt</i>	To set controller Resolution for Temperature
3	<i>P2</i>	To Set Maximum Allowable High Temperature Limit
4	<i>P3</i>	To Set Minimum Allowable Low Temperature Limit
5	<i>Adt</i>	Power On Time Delay for Alarm for Temperature (Ht and Lt)
6	<i>P5</i>	Temperature Probe Calibration
7	<i>SSL</i>	4-20 mA input selection for RH or Pressure
8	<i>H55</i>	Selection of RH Sensor
9	<i>rSH</i>	To set controller Resolution for RH
10	<i>H2</i>	To Set Maximum Allowable High Humidity Limit
11	<i>H3</i>	To Set Minimum Allowable Low Humidity Limit
12	<i>AdH</i>	Power On Time Delay for Alarm for RH (HH and LH)
13	<i>H5</i>	RH Probe Calibration
14	<i>PrH</i>	Pressure high range selection for 20mA
15	<i>PrL</i>	Pressure low range selection for 4mA


16	<i>Pr2</i>	To Set Maximum Allowable High Pressure Limit
17	<i>Pr3</i>	To Set Minimum Allowable Low Pressure Limit
18	<i>AdP</i>	Power On Time Delay for Alarm for pressure (HP and LP)
19	<i>Pr5</i>	Pressure Probe Calibration
20	<i>nd</i>	Default (Normal) Display
21	<i>tnd</i>	Flashing rate for multiple sensor selection
22	<i>RL</i>	Alarm indication configuration for alarm icon and display fault messages
23	<i>LP</i>	Keypad Lock
24	<i>F5</i>	Factory Set
25	<i>EP</i>	End Programming
		LED Indications
		Fault Messages
		Operating Messages
		High and Low Temperature, Humidity and Pressure Logging Function


PARAMETER LIST

To set parameters,		Display will flash “ <i>ntC</i> ”.
Press & hold  key for 2 seconds.		To select other parameters, use  key.

1. *ntC*

Function: Temperature probe and Unit selection.

To change value use  key

To set value press  key

If this parameter is set to,
dS = NTC Probe disabled
C = Unit °C (Temperature and related parameters will be displayed in unit °C)
F = Unit °F (Temperature and related parameters will be displayed in unit °F)
If Unit changed, *P2* and *P3* changed to Factory settings of respective Unit.

Min	Max	Fac.
<i>dS</i>	<i>F</i>	-

Note: If *ntC* disabled, *rSt*, *P2*, *P3*, *Adt* and *P5* will not work and can not be displayed. Also, If *ntC* set to *F*, *rSt* will not work and can not be displayed.

2. *rSt*

Function: To set controller Resolution for Temperature.

If this parameter is set to,
0.1 = 0.1°C Resolution
Temperature and related parameters will be displayed with 0.1°C Resolution.
1 = 1°C Resolution
Temperature and related parameters will be displayed with 1°C Resolution.

Min	Max	Fac.
<i>0.1</i>	<i>1</i>	-


Note: If *ntC* disabled or set to *F*, *rSt* will not work and can not be displayed.

3. *P2*

Function: To Set Maximum Allowable High Temperature Limit.

Example: If this parameter is set to 99.0°C and the Temperature reaches or goes above 99.0°C, Display will show *Ht* (High Temperature) indicating that the Temperature has reached or gone above the value set in this parameter.

rS = 0.1, ntC = C		
Min	Max	Fac.
<i>P3</i> +1.0	99.0°C	99.0°C

Ht 

(Message on display)

rS = 1, ntC = C		
Min	Max	Fac.
<i>P3</i> +1	99°C	99°C

ntC = F		
Min	Max	Fac.
<i>P3</i> +1	210°F	210°F


Note: If *ntC* disabled, or *RL* is set to 0, *P2* will not work and can not be displayed.

4. *P3*

Function: To Set Minimum Allowable Low Temperature Limit.

Example: If this parameter is set to -10.0°C and the Temperature reaches or goes below -10.0°C, Display will show *Lt* (Low Temperature) indicating that the Temperature has reached or gone below the value set in this parameter.

rS = 0.1, ntC = C		
Min	Max	Fac.
-50.0°C	<i>P2</i> -1.0	-50.0°C

Lt 

(Message on display)

rS = 1, ntC = C		
Min	Max	Fac.
-50°C	<i>P2</i> -1	-50°C

ntC = F		
Min	Max	Fac.
-58°F	<i>P2</i> -1	-58°F

Note: If *ntC* disabled, or *RL* is set to 0, *P3* will not work and can not be displayed.

5. *Adt*

Function: Power On Time Delay For Alarm for Temperature

Example: If this parameter is set to 20 minutes, once the indicator is powered ON, High Temperature and Low Temperature fault indication will not be activated for 20 minutes.

If Probe Temperature reaches or goes above *P2* parameter value, High Temperature (*Ht*) fault will be displayed after completion of delay set with *Adt* parameter.

If Probe Temperature reaches or drops below *P3* parameter value, Low Temperature (*Lt*) fault will be displayed after completion of delay set with *Adt* parameter.

Differential of 0.1°C / 1°C / 1°F is considered for clearing the fault.

Min	Max	Fac.
0 min	99 min	20 min

Note: If *ntC* disabled, or *RL* is set 0, *Adt* will not work and can not be displayed.

6. *P5*

Function: Temperature Probe Calibration

In time it may be possible that the display may be offset by a degree or so.

To compensate for this error, user may need to add or minus the degrees required to achieve the correct Temperature.

Example: The Temperature on the display is 28.0°C, whereas the actual Temperature is 30.0°C. User will have to set the *P5* parameter to 2.0 °C, which means that once out of the Programming Mode, the Temperature on display will be 30.0°C (28.0°C+ 2.0°C)

rS = 0.1, ntC = C		
Min	Max	Fac.
-10.0	10.0	0.0

rS = 1, ntC = C		
Min	Max	Fac.
-10	10	0

ntC = F		
Min	Max	Fac.
-10	10	0

Note: If *ntC* disabled, *P5* will not work and can not be displayed.

7. *SSL*

Function: 4-20 mA input selection for RH or Pressure

If this parameter is set to,
dS = 4-20 mA input disabled
rH = 4-20 mA input is selected for RH
Pr = 4-20 mA input is selected for Pressure

Min	Max	Fac.
<i>dS</i>	<i>Pr</i>	<i>dS</i>

Note: If *SSL* is set to *dS* or *rH* then, *PrH*, *PrL*, *Pr2*, *Pr3*, *AdP* and *Pr5* will not work and can not be displayed. Also, If *SSL* is set to *rH* then, *H55* will not work and can not be displayed.

8. *H55*

Function: Selection of RH Sensor

If this parameter is set to,
dS = RH sensor disabled
H51 = HS-100 is selected as RH sensor
H52 = HS-220 is selected as RH sensor

Min	Max	Fac.
<i>dS</i>	<i>H52</i>	<i>dS</i>

Note: If *H55* disabled and *SSL* is other than *rH*, then *rSH*, *H2*, *H3*, *AdH* and *H5* will not work and can not be displayed.

9. *rSH*

Function: To set controller Resolution for RH

If this parameter is set to,
0.1 = 0.1% Resolution
RH and related parameters will be displayed with 0.1% Resolution.
1 = 1% Resolution
RH and related parameters will be displayed with 1% Resolution.

Min	Max	Fac.
<i>0.1</i>	<i>1</i>	-

Note: If *H55* disabled and *SSL* is other than *rH*, then *rSH* will not work and can not be displayed.


10. *H2*

Function: To Set Maximum Allowable High Humidity Limit.

Example: If this parameter is set to 90.0% and the Humidity reaches or goes above 90.0%, Display will show *HH* (High Humidity) indicating that the Humidity has reached or gone above the value set in this parameter.

HS-220					
rSH = 0.1			rSH = 1		
Min	Max	Fac.	Min	Max	Fac.
<i>H3</i> +1.0	90.0%	90.0%	<i>H3</i> +1	90%	90%


HS-100 / 4-20mA					
rSH = 0.1			rSH = 1		
Min	Max	Fac.	Min	Max	Fac.
<i>H3</i> +1.0	99.0%	99.0%	<i>H3</i> +1	99%	99%





HH 

(Message on display)

Note: If *H55* disabled and *SSL* is other than *rH*, or *RL* is set 0, then *H2* will not work and can not be displayed.



11.	H3	Function: To Set Minimum Allowable Low Humidity Limit.										
Example: If this parameter is set to 30.0% and the Humidity reaches or goes below 30.0%, Display will show LH (Low Humidity) indicating that the Humidity has reached or gone below the value set in this parameter.												
<div>LH</div> <div>(Message on display)</div>	HS-220											
	rSH = 0.1			rSH = 1								
	Min	Max	Fac.	Min	Max	Fac.						
	30.0%	H2-1.0%	30.0%	30%	H2-1%	30%						
	HS-100 / 4-20mA											
	rSH = 0.1			rSH = 1								
Min			Max			Fac.						
0.0%			H2-1.0%			0.0%						
Min			Max			Fac.						
0.0%			H2-1%			0%						
Note: If H55 disabled and 55L is other than rH, or RL is set 0, then H3 will not work and can not be displayed.												
12.	RdH	Function: Power on Time Delay for Alarm for RH										
Example: If this parameter is set to 20 minutes, once the indicator is powered ON, High Humidity and Low Humidity fault indication will not be activated for 20 minutes.												
If Humidity reaches or goes above H2 parameter value, High Humidity (HH) fault will be displayed after completion of delay set with RdH parameter.												
If Humidity reaches or drops below H3 parameter value, Low Humidity (LH) fault will be displayed after completion of delay set with RdH parameter.												
Differential of 0.1% / 1% is considered for clearing the fault.												
<table><tr><td>Min</td><td>Max</td><td>Fac.</td></tr><tr><td>0 min</td><td>99 min</td><td>20 min</td></tr></table>							Min	Max	Fac.	0 min	99 min	20 min
Min	Max	Fac.										
0 min	99 min	20 min										
Note: If H55 disabled and 55L is other than rH, or RL is set 0, then RdH will not work and can not be displayed.												
13.	H5	Function: RH Probe Calibration										
In time it may be possible that the display may be offset by a percent or so.												
To compensate for this error, user may need to add or minus the percents required to achieve the correct Humidity.												
Example: The Humidity on the display is 50.0%, whereas the actual Humidity is 52.0%. User will have to set the H5 parameter to 2.0%, which means that once out of the Programming Mode, the Humidity on display will be 52.0% (50.0%+2.0%) .												
<table><tr><td>Min</td><td>Max</td><td>Fac.</td></tr><tr><td>-10.0%</td><td>10.0%</td><td>0.0%</td></tr></table>							Min	Max	Fac.	-10.0%	10.0%	0.0%
Min	Max	Fac.										
-10.0%	10.0%	0.0%										
Note: If H55 disabled and 55L is other than rH, then H5 will not work and can not be displayed.												
14.	PrH	Function: Pressure high range selection for 20mA										
The value set with this parameter is the pressure high range value selected for 20mA.												
Example: If this parameter is set to 600 PSI, for pressure above 600 PSI, display will show Pressure probe fail PrF message.												
<table><tr><td>Min</td><td>Max</td><td>Fac.</td></tr><tr><td>(PrL+1) PSI</td><td>600 PSI</td><td>600 PSI</td></tr></table>							Min	Max	Fac.	(PrL+1) PSI	600 PSI	600 PSI
Min	Max	Fac.										
(PrL+1) PSI	600 PSI	600 PSI										
Note: If 55L is other than Pr, then PrH will not work and can not be displayed.												
15.	PrL	Function: Pressure low range selection for 4mA										
The value set with this parameter is the pressure low range value selected for 4mA.												
Example: If this parameter is set to -15 PSI, for pressure below -15 PSI, display will show Pressure probe fail PrF message.												
PrH and PrL parameters decide the operating range for pressure sensor against 4-20mA input.												
<table><tr><td>Min</td><td>Max</td><td>Fac.</td></tr><tr><td>-15 PSI</td><td>(PrH-1) PSI</td><td>-15 PSI</td></tr></table>							Min	Max	Fac.	-15 PSI	(PrH-1) PSI	-15 PSI
Min	Max	Fac.										
-15 PSI	(PrH-1) PSI	-15 PSI										
Note: If 55L is other than Pr, then PrL will not work and can not be displayed.												
16.	Pr2	Function: To Set Maximum Allowable Low Pressure Limit.										
Example: If this parameter is set to 500 PSI and the Pressure reaches or goes above 500 PSI, Display will show HPr (High Pressure) indicating that the Pressure has reached or gone above the value set in this parameter.												
<table><tr><td>Min</td><td>Max</td><td>Fac.</td></tr><tr><td>(Pr3+1) PSI</td><td>PrH</td><td>600 PSI</td></tr></table>							Min	Max	Fac.	(Pr3+1) PSI	PrH	600 PSI
Min	Max	Fac.										
(Pr3+1) PSI	PrH	600 PSI										
Note: If 55L is other than Pr, or RL is set 0, then Pr2 will not work and can not be displayed.												
17.	Pr3	Function: To Set Minimum Allowable Low Pressure Limit.										
Example: If this parameter is set to 10 PSI and the Pressure reaches or goes below 10PSI, Display will show LPr (Low Pressure) indicating that the Pressure has reached or gone below the value set in this parameter.												
<table><tr><td>Min</td><td>Max</td><td>Fac.</td></tr><tr><td>PrL</td><td>(Pr2-1) PSI</td><td>-15 PSI</td></tr></table>							Min	Max	Fac.	PrL	(Pr2-1) PSI	-15 PSI
Min	Max	Fac.										
PrL	(Pr2-1) PSI	-15 PSI										
Note: If 55L is other than Pr, or RL is set 0, then Pr3 will not work and can not be displayed.												







18.	<i>RdP</i>	Function: Power on Time Delay for Alarm for pressure						
Example: If this parameter is set to 20 minutes, once the indicator is powered ON, High Pressure and Low Pressure fault indication will not be activated for 20 minutes. If Pressure reaches or goes above <i>Pr2</i> parameter value, High Pressure (<i>HPr</i>) fault will be displayed after completion of delay set with <i>RdP</i> parameter. If Pressure reaches or drops below <i>Pr3</i> parameter value, Low Pressure (<i>LPr</i>) fault will be displayed after completion of delay set with <i>RdP</i> parameter. Differential of 10 PSI is considered for clearing the fault.								
<table><tr><td>Min</td><td>Max</td><td>Fac.</td></tr><tr><td>0 min</td><td>99 min</td><td>20 min</td></tr></table>			Min	Max	Fac.	0 min	99 min	20 min
Min	Max	Fac.						
0 min	99 min	20 min						
Note: If 55L is other than <i>Pr</i> , or <i>RL</i> is set 0, then <i>RdP</i> will not work and can not be displayed.								
19.	<i>Pr5</i>	Function: Pressure Probe Calibration						
In time it may be possible that the display may be offset by a PSI or so. To compensate for this error, user may need to add or minus the PSI required to achieve the correct Pressure. Example: The Pressure on the display is 100 PSI, whereas the actual Pressure is 105 PSI. User will have to set the <i>Pr5</i> parameter to 5 PSI, which means that once out of the Programming Mode, the Pressure on display will be 105 PSI (100 PSI+ 5 PSI).								
<table><tr><td>Min</td><td>Max</td><td>Fac.</td></tr><tr><td>-20 PSI</td><td>20 PSI</td><td>0 PSI</td></tr></table>			Min	Max	Fac.	-20 PSI	20 PSI	0 PSI
Min	Max	Fac.						
-20 PSI	20 PSI	0 PSI						
Note: If 55L is other than <i>Pr</i> , then <i>Pr5</i> will not work and can not be displayed.								
20.	<i>nd</i>	Function: Default (Normal) Display						
If this parameter is set to, LtP = Default display will be Temperature rH = Default display will be Humidity Pr = Default display will be Pressure ALL = Display will show the Temperature, Humidity and Pressure one by one with the time set in <i>End</i> parameter.								
<table><tr><td>Min</td><td>Max</td><td>Fac.</td></tr><tr><td>LtP</td><td>RL L</td><td>LtP</td></tr></table>			Min	Max	Fac.	LtP	RL L	LtP
Min	Max	Fac.						
LtP	RL L	LtP						
21.	<i>End</i>	Function: Flashing rate for multiple sensor selection						
Example: If this parameter is set to 2 seconds and <i>nd</i> parameter is set to <i>RL L</i> , then display will show the Temperature, Humidity and Pressure one by one each for 2 seconds for all enabled sensors. If any High / Low temperature, Humidity or Pressure fault is present then it will flash at the rate of 500ms with respective sensor value.								
<table><tr><td>Min</td><td>Max</td><td>Fac.</td></tr><tr><td>1 sec.</td><td>999 sec.</td><td>2 sec.</td></tr></table>			Min	Max	Fac.	1 sec.	999 sec.	2 sec.
Min	Max	Fac.						
1 sec.	999 sec.	2 sec.						
22.	<i>AL</i>	Function: Alarm indication configuration for alarm icon and display fault messages						
If this parameter is set to, 0 = Alarm indication is applicable to all sensor fail faults and related fault massages (<i>PrF</i> , <i>PP</i> , <i>HPP</i>) will be displayed. 1 = Alarm indication is applicable to all faults and all fault messages will be displayed (<i>Ht</i> , <i>Lt</i> , <i>HH</i> , <i>LH</i> , <i>HPr</i> , <i>LPr</i> , <i>PrF</i> , <i>PP</i> , <i>HPP</i>).								
<table><tr><td>Min</td><td>Max</td><td>Fac.</td></tr><tr><td>0</td><td>1</td><td>0</td></tr></table>			Min	Max	Fac.	0	1	0
Min	Max	Fac.						
0	1	0						
Note : If <i>RL</i> parameter is set to 0, Parameters <i>P2</i> , <i>P3</i> , <i>Rdt</i> , <i>H2</i> , <i>H3</i> , <i>RdH</i> , <i>Pr2</i> , <i>Pr3</i> , <i>RdP</i> not work and can not be displayed.								
23.	<i>LP</i>	Function: To Lock Keypad.						
This parameter is used to lock the keypad so that tampering is not possible by by-standers. UnL = Keypad locked LoC = Keypad unlocked When locked all parameters can only be viewed, but not modified.								
<table><tr><td>Min</td><td>Max</td><td>Fac.</td></tr><tr><td>UnL</td><td>LoC</td><td>UnL</td></tr></table>			Min	Max	Fac.	UnL	LoC	UnL
Min	Max	Fac.						
UnL	LoC	UnL						
Note : If <i>LP</i> parameter is set to 1 and if user tries to change any parameter value, "LP" will flash on the display.								
24.	<i>F5</i>	Function: To Factory Set.						
When set to YES all parameters are programmed to factory set values. Useful to debug setting related Problems. When set to, no = FS is disable. YES = FS as per default value.								
<table><tr><td>Min</td><td>Max</td><td>Fac.</td></tr><tr><td>no</td><td>YES</td><td>no</td></tr></table>			Min	Max	Fac.	no	YES	no
Min	Max	Fac.						
no	YES	no						
25.	<i>EP</i>	Function: To End Programming.						
To End Programming Press  key								
Once the key is pressed, the indicator goes into the normal mode and displays the Temperature/ Humidity/ Pressure as per <i>nd</i> parameter and all settings are recorded.								

LED INDICATION			
LED	Status	Description	Parameter
	ON	Alarm indication is ON for all faults : <i>Ht</i> , <i>Lt</i> , <i>PP</i> , <i>HH</i> , <i>LH</i> , <i>HPP</i> , <i>PrF</i> , <i>HPr</i> , <i>LPr</i> .	<i>P2</i> , <i>P3</i> , <i>H2</i> , <i>H3</i> , <i>Pr2</i> , <i>Pr3</i> , <i>RL</i>
	ON	NTC Probe Temperature and Temperature related parameters displayed in °C.	<i>nLt</i>
	ON	NTC Probe Temperature and Temperature related parameters displayed in °F.	
	ON	RH and RH related parameters displayed.	<i>55L</i> , <i>H55</i>
PSI	ON	Pressure and Pressure related parameters displayed.	<i>55L</i>

FAULT MESSAGES		
Msg.	Description	Para.
<i>PP</i>	Temperature Probe Fail Probe short circuit, circuit open or without probe, or Temperature is > 100°C or < -50.0°C (if parameter <i>nLt</i> is set to °C) or > 212°F or < -58°F (if parameter <i>nLt</i> is set to °F).	<i>nLt</i>
<i>HPP</i>	RH Probe Fail Probe short circuit, circuit open or without probe, or Humidity is >100 % or < 0.0% (SZ-HS-100 / 4-20mA) or Humidity is >90.0 % or < 30.0% (SZ-HS-220).	<i>55L</i> , <i>H55</i>
<i>PrF</i>	Pressure Probe Fail Probe short circuit, circuit open or without probe, or Pressure is > Parameter <i>PrH</i> PSI or < Parameter <i>PrL</i> PSI.	<i>55L</i>
<i>Ht</i>	High Temperature Alarm Temperature above the maximum high Temperature Limit.	<i>P2</i> , <i>RL</i>
<i>Lt</i>	Low Temperature Alarm Temperature below the minimum low Temperature Limit.	<i>P3</i> , <i>RL</i>
<i>HH</i>	High RH Alarm Humidity above the maximum high RH Limit.	<i>H2</i> , <i>RL</i>
<i>LH</i>	Low RH Alarm Humidity below the minimum low RH Limit.	<i>H3</i> , <i>RL</i>
<i>HPr</i>	High Pressure Alarm Pressure above the maximum high Pressure Limit.	<i>Pr2</i> , <i>RL</i>
<i>LPr</i>	Low Pressure Alarm Pressure below the minimum low Pressure Limit.	<i>Pr3</i> , <i>RL</i>

OPERATING MESSAGES		
<i>Lr5</i>	In Log function: When <i>LL 1</i> - <i>LL3</i> and <i>LH 1</i> - <i>LH3</i> values are cleared.	-
<i>LL 1</i>	Last Low Temperature Las Low Temperature Logged.	<i>nLt</i>
<i>LH 1</i>	Last High Temperature Las High Temperature Logged.	
<i>LL2</i>	Last Low Humidity Las Low Humidity Logged.	<i>55L</i> , <i>H55</i>
<i>LH2</i>	Last High Humidity Las High Humidity Logged.	
<i>LL3</i>	Last Low Pressure Las Low Pressure Logged.	<i>55L</i>
<i>LH3</i>	Last High Pressure Las High Pressure Logged.	
<i>r5 1</i>	When <i>LL 1</i> and <i>LH 1</i> values of NTC are reset when NTC fails or NTC sensor is not Selected.	-
<i>r52</i>	When <i>LL2</i> and <i>LH2</i> values of RH are reset when RH fails or RH sensor is not Selected.	-
<i>r53</i>	When <i>LL3</i> and <i>LH3</i> values of Pressure Probe are reset when Pressure Probe fails or Pressure Probe is not Selected.	-
<i>LP</i>	Keypad lock Keypad is locked.	<i>LP</i>
<i>Lpd</i>	When <i>nd</i> is set to <i>LtP</i> and <i>nLt</i> is set to <i>d 15</i> .	<i>nLt</i>
<i>rHd</i>	When <i>nd</i> is set to <i>rH</i> and <i>55L</i> is other than <i>rH</i> and <i>H55</i> is set to <i>d 15</i> .	<i>55L</i> , <i>H55</i>
<i>Prd</i>	When <i>nd</i> is set to <i>Pr</i> and <i>55L</i> is other than <i>Pr</i> .	<i>55L</i>
<i>RLd</i>	When <i>nd</i> is set to <i>RL L</i> and all sensors are disabled.	<i>nLt</i> , <i>55L</i> , <i>H55</i>

HIGH AND LOW TEMPERATURE, HUMIDITY AND PRESSURE LOGGING FUNCTION	
How to see the Logged Values: <i>LL 1</i> : Last Low Temperature <i>LH 1</i> : Last High Temperature <i>LL2</i> : Last Low RH <i>LH2</i> : Last High RH <i>LL3</i> : Last Low Pressure <i>LH3</i> : Last High Pressure	
Press and hold  key for 4sec, initially indicator enter into to Sensor display mode and after 4 seconds it will enter in Min./Max. Log mode.	
Temperature log : Display will flash “ <i>LL 1</i> ” and the corresponding temperature for 4 seconds. After this, display will flash “ <i>LH 1</i> ” and the corresponding Temperature for 4 seconds.	
Humidity log : After Temperature log, display will flash “ <i>LL2</i> ” and the corresponding Humidity for 4 seconds. After this, display will flash “ <i>LH2</i> ” and the corresponding Humidity for 4 seconds.	
Pressure log : After Humidity log, display will flash “ <i>LL3</i> ” and the corresponding Pressure for 4 seconds. After this, display will flash “ <i>LH3</i> ” and the corresponding Pressure for 4 seconds and come out of Log Mode and will display the Temperature/ Humidity/ Pressure as per <i>nd</i> parameter.	
How to reset the Logged Values While the display is showing the Logged Values, if user press & hold the  key for 2sec, the Logged Values will be cleared and reset message will be displayed as below, <i>r5 1</i> : Temperature log reset <i>r52</i> : Humidity log reset <i>r53</i> : Pressure log reset Log Values will get reset after Power ON/OFF.	

Disclaimer: These manual & its contents remain the sole property of PVR CONTROLS, India and shall not be reproduced or distributed without authorization. Although great care has been taken in the preparation of this document, the firm or its vendors in no event will be liable for direct, indirect, special, incidental, or consequential damage arising out of the use or inability to use the product or documentation, even if advised of the possibility of such damages. Prospective purchasers should not confine themselves to the contents but should make their own enquiries to satisfy themselves in all respects. No part of this manual may be reproduced or transmitted in any form or by any means without the prior written permission of the firm. PVR CONTROLS, reserves the right to make and changes or improvements without prior notice. PVR CONTROLS will not accept any responsibility should any details prove to be incomplete or incorrect. PVR CONTROLS assumes no responsibility for any misleading content, or incorrectly listed information due to inaccuracies in content or data supplied by any source to the information available. Warranty: This product is warranted against defects in materials and workmanship for a period of one year from the date of purchase. During the warranty period, product determined by us to be defective in form or function will be repaired or, at our option, replaced at no charge. Such rectification shall be provided / carried out only upon submitting a valid purchase receipt. Any claim raised after warranty period shall not be entertained. This warranty does not apply if the product has been damaged by accident, abuse, willful default on part of the user, negligent use, and misuse or as a result of service or modification other than by the firm. (De)mounting and/or (de)installation, and labor costs are excluded from warranty. In no event shall the firm be held liable for incidental or consequential damages, including loss of revenue or loss of business opportunity arising from the purchase of this product nor compensate you for any reason whatsoever.							
<table><tr><th colspan="2">OTHER PRODUCTS</th></tr><tr><td> Controlled cooling, always</td><td></td></tr><tr><td>Cold Room Controller Chiller Controller Two Compressor Controller Heating Controller Humidity Controller Pressure Controller</td><td>Shut Off Valve Solenoid Valve Ball Valve Hand Valve Flow Switch Door Latch / Hinges</td></tr></table>		OTHER PRODUCTS		 Controlled cooling, always		Cold Room Controller Chiller Controller Two Compressor Controller Heating Controller Humidity Controller Pressure Controller	Shut Off Valve Solenoid Valve Ball Valve Hand Valve Flow Switch Door Latch / Hinges
OTHER PRODUCTS							
 Controlled cooling, always							
Cold Room Controller Chiller Controller Two Compressor Controller Heating Controller Humidity Controller Pressure Controller	Shut Off Valve Solenoid Valve Ball Valve Hand Valve Flow Switch Door Latch / Hinges						
REV1 –24.04.2023							