

- 
Blue Back-light
- 
Low Battery Indicator
- 
Temperature Display
- 
Capacity 180Kg
- 
LCD Display
- 
Automatic Off
- 
Accurate Reading
- 
Overload Indicator
- 
Unit Kg/Lb/St
- 
Instant Step On Technology

WS-101 Weighing Machine

Features:

- Instant Step On Technology
- Temperature Display
- Overload Indicator
- Long Battery Life
- Low Battery Indicator
- Multiple Units Display
- High Accuracy
- Auto On/Off

Specifications:

Capacity	180kg
Auto off/On	After 10 seconds
Units	kg/lb/st
Graduation	10gm
Display	LCD
Back-light	Blue backlit display
Temperature Display	Displayed on screen
Overload Indicator	After 180kg

How to Use:



Insert the Batteries.



Select the scale unit (Kg /Lb/St).




Put scale on a flat surface. Step on the weighing Machine.



Stay still to see the result.

Contact us:

 Mobile No./ WhatsApp No. : +91 9310113243

 Web : www.klifecare.com

 Email : info@klifecare.com