






 Low Battery Indicator	 Capacity 200Kg	 LED Display	 Automatic Off	 Accurate Reading	 Overload Indicator	 Unit Kg/Lb/St	 Instant Step On Technology
---	---	--	--	---	---	--	---

WS-103 Weighing Machine





Features:

- Instant Step On Technology
- Temperature Display
- Overload Indicator
- Low Battery Indicator
- Multiple Units Display
- High Accuracy
- Auto On/Off

Specifications:

Capacity	180kg
Auto off/On	After 10 seconds
Units	kg/lb/st
Graduation	10gm
Display	LCD
Back-light	Blue backlit display
Temperature Display	Displayed on screen
Overload Indicator	After 180Kg

How to Use:

- 
Insert the Batteries.
- 
Select the scale unit (Kg/Lb/St).
- 
Step on the weighing Machine.
- 
Stay still to see the result.

Contact us:

	Mobile No./ WhatsApp No. : +91 9310113243
	Web : www.klifecare.com
	Email : info@klifecare.com