




(ISO 9001 CERTIFIED COMPANY)

SUMIT ENGINEERING WORKS


20, MAHALAXMI COMPOUND, OPP. RAVI ESTATE,
NR. J.K. ESTATE, DUDHESHWAR ROAD,
AHMEDABAD-380 004 (GUJARAT) Ph. NO. 079-25627942
GOVIND PANCHAL: 9687280181 RAMESH PANCHAL: 9825835180
EMAIL: sumiteng1994@yahoo.co.in, www.sumitengg.in
sumiteng1994@gmail.com, www.acdcmotors.in



AC SYNCHRONUS
MOTOR



AC SYNCHRONUS
WORM GEAR MOTOR



AC SYNCHRONUS
INLINE GEAR MOTOR



PMDC MOTOR



PMDC WORM GEAR
MOTOR




PMDC PLANETARY
INLINE GEAR MOTOR



AC INDUCTION
MOTOR



AC INDUCTION WORM
GEAR MOTOR



AC INLINE GEAR
MOTOR

* AC SYNCHRONUS MOTOR


3/7 KG/CM



10/15 KG/CM



20/30 KG/CM



40/60 KG/CM




INPUT SUPPLY: 240 V AC , 1 PH, 50 HZ , 60 RPM , INSTANT START/STOP & REVERSE **TORQUE:** 3 / 7 / 10 / 15 / 20 / 30 / 40 / 60 KG/CM . DIMENTIONS ARE SHOWN IN TABLE.

10 w




7 KG



10 KG



20/30/40/60 KG




• AC SYNCHRONUS GEAR MOTOR

INPUT SUPPLY: 240 V AC, 50 HZ , 0.06 TO 60 RPM , INSTANT START/STOP & REVERSE , **TORQUE:** 7 / 10 / 15 / 20 / 30 / 40 / 60 KG/CM , DIMENTIONS ARE SHOWN IN TABLE.

SYNCHRONUS MOTOR DIMENTIONS

KG/CM	A	B	C	D	E	F	G	H	PCD	WEIGHT
3	86	86	10	8	30	5	20	65	100	1.5kg
7	86	86	10	8	30	5	20	65	100	1.5kg
10	108	108	10	8	40	6	30	75	123	2.5kg
15	108	108	10	8	40	6	30	75	123	2.5kg
20	108	108	10	8	35	6	20	102	123	3.5kg
30	108	108	10	8	35	6	20	102	123	3.5kg
40	110	110	15	8	50	7	35	156	123	7.0kg
60	110	110	15	8	50	7	35	156	123	7.0kg



*ALL DIMENTIONS ARE IN MM.

* **PMDC MOTOR**

5/10 W



20/30 W



50 W



100/150 W



200/300 W



400/750 W



INPUT SUPPLY: 12 TO 180 VOLT DC, 1000 TO 5000 RPM , 5 W TO 750 WATTS

MOUNTING: FOOT / FLANGE / FACE

• **PMDC WARM GEAR MOTOR**

50 W



100/150 W



200/300 W



400/750 W



INPUT SUPPLY: 12 TO 180 VOLT DC, 10 TO 500 RPM , 50 TO 750 WATTS.

MOUNTING: FOOT / FLANGE / FACE

• **PMDC PLANETARY GEAR MOTOR**

5/10 W



25 W



50W



100/150 W



200/300 W



400/750 W




CENTRE SHAFT / OFF CENTRE SHAFT

INPUT SUPPLY: 12 TO 180 VOLT DC, 10 TO 500 RPM, 5 W TO 750 WATT

MOUNTING: FOOT / FLANGE / FACE

* AC INDUCTION MOTOR



• AC INDUCTION MOTOR

INPUT SUPPLY: 230 / 440
VOLT AC 1 & 3 PHASE
RPM: 1440 / 2880 RPM
HP: 0.12 TO 1 HP




• AC WARM GEAR MOTOR

INPUT SUPPLY: 230 / 440
VOLT AC 1 & 3 PHASE
RPM: 15 TO 400 RPM
HP: 0.12 TO 1 HP



• AC INLINE GEAR MOTOR

INPUT SUPPLY: 230 / 440 VOLT AC
1 & 3 PHASE
RPM: 15 TO 400 RPM
HP: 0.12 TO 1 HP



• LOCATION

