

COMPANY : M/S BHARAT FORGE LTD MUNDHAWA, PUNE

PROBLEM REPORTED : Enamel paint coated to LPG bullets, forms flakes and needed Recoating every year. The temp of bullet top surface used to Cross 50deg C in summer and needed cooling through sprinklers every day thereby increasing energy and resources costs.

SOLUTIONS PROPOSED : Coating LPG bullets with UGAM INSULMIX COATING SYSTEM FOR LPG BULLETS.

SAVINGS ACHIEVED AT BHARAT FORGE LTD. PUNE.

TOTAL WATER, ELECTRICITY AND PAINTING COST SAVING=758175.00

The coating is completed on 15 May 2006.

