
Low Battery Indicator	Capacity 200Kg	LED Display	Automatic Off	Accurate Reading	Overload Indicator	Unit Kg/Lb/St	Instant Step On Technology

WS-102 Weighing Machine


Features:

- Instant Step On Technology
- Overload Indicator
- Long Battery Life
- Low Battery Indicator
- Multiple Units Display
- High Accuracy
- Auto On/Off


Specifications:

Capacity	200kg
Auto off/On	After 10 seconds
Units	kg/lb/st
Graduation	10gm
Display	LED
Temperature Display	Displayed on screen

How to Use:



Insert the Batteries.



Select the scale unit (Kg /Lb/St).





Place the weighing machine on a flat surface. Step on the weighing Machine.




Stay still to see the result.

Contact us:

 Mobile No./ WhatsApp No. : +91 9310113243

 Web : www.klifacare.com

 Email : info@klifacare.com