

# PRODUCTIVE ENGINEERS (I) PVT LTD

## LIST OF INSTRUMENTS

SR NO.	NAME OF INSTRUMENTS
1.	MICROMETER – IN HOUSE & OUTSOURCED
2.	VERNIER CALIPER - IN HOUSE & OUTSOURCED
3.	CLAMP METER - IN HOUSE
4.	DFT METER - IN HOUSE
5.	DUMPY LEVEL - IN HOUSE
6.	WELD GAUGE - IN HOUSE
7.	SPIRIT LEVEL - IN HOUSE
8.	MEASURING TAPE - IN HOUSE & OUTSOURCED
9.	TRY SQUIRE - IN HOUSE
10.	SURFACE ROUGHNESS TESTER – IN HOUSE & OUTSOURCED
11.	TEMPERATURE GAUGE – DIGITAL OUTSOURCED
12.	HUMIDITY METER – DIGITAL OUTSOURCED
13.	ULTRASONIC THICKNESS GAUGE - OUTSOURCED

# PRODUCTIVE ENGINEERS (I) PVT LTD



MICROMETER

# PRODUCTIVE ENGINEERS (I) PVT LTD



# VERNIER CALIPER

# PRODUCTIVE ENGINEERS (I) PVT LTD



## CLAMP METER

# PRODUCTIVE ENGINEERS (I) PVT LTD



**DFT METER**

# PRODUCTIVE ENGINEERS (I) PVT LTD



**DUMPY LEVEL**

# PRODUCTIVE ENGINEERS (I) PVT LTD



**WELD GAUGE**

# PRODUCTIVE ENGINEERS (I) PVT LTD



**SPIRIT LEVEL**

# PRODUCTIVE ENGINEERS (I) PVT LTD



## MEASURING TAPE

# PRODUCTIVE ENGINEERS (I) PVT LTD



TRY SQUARE

# PRODUCTIVE ENGINEERS (I) PVT LTD



## SURFACE ROUGHNESS TESTER