

Foundation Structure Image Description



This image shows a reinforced concrete foundation footing under construction. A steel reinforcement cage (rebar column) is positioned vertically at the center of the concrete base. The footing appears freshly cast with wet concrete spread evenly across the excavated foundation pit. Surrounding soil and construction materials indicate an active construction site, likely for a building or structural column support.