

PHOTO REPORT

Page No.1 of 9



Cargo offered in packed condition in drums



All drums completely emptied on clean and dry tarpauline for inspection



Total material emptied out from all 10 drums



Material observed free from foreign material & slag contamination (close view)



PHOTO REPORT

Page No.2 of 9



One more close view of material - showing material is free from foreign material & slag contamination



Mixing of total materil by making cone is in progress



Collection of Sample increment for Chemical analysis & Sieve analysis from the flattened material




Sample collected for Sieve analysis



PHOTO REPORT

Page No.3 of 9

REF: BO2032221 –SK/A DATE: 07.07.2020






Sieving in progess to check materil below 10 MM size in progress

Sieving in progess to check material below 10 MM size in progress







Calibration Checked for Weigh Balance – found in order



PHOTO REPORT

Page No.4 of 9



Material passed through 10 MM sieve checked for weight



Sample collected for Chemical Analysis



Sample Crushing in progress to get (-)10 MM size



Crusher details used to crush -10 MM



PHOTO REPORT

Page No.5 of 9



Sample preparation in process



Gross Sample completely crushed to -10 MM (55 kgs)



Gross sample mixed properly (-10 MM)



Sample size reduced to 7 kg by I.R. Method (3 stages)



PHOTO REPORT

Page No.6 of 9

REF: BO2032221 –SK/A DATE: 07.07.2020



Total 7 kgs (- 10 MM) further crushed to -2.0 MM mixed up properly.



Sample spread uniformly for I.R.



Sample size reduced to 400 gm by I.R. Method (3 stages)



Total 400 gm (- 2 MM) pulverised to 150 Micron mixed up properly spread uniformly for I.R.




eReport No. 20070806E2 PHOTO REPORT

Page No.7 of 9

REF: BO2032221 -SK/A DATE: 07.07.2020







Checked Tare wt of Individual drum



Individual drum checked for Tare wt



Individual drum checked for Gross wt.




eReport No. 20070806E2 PHOTO REPORT

Page No.8 of 9

REF: BO2032221 -SK/A DATE: 07.07.2020



Individual drum checked for Gross wt.



Drums sealed with SGS Numbered plastic wire seal



Drums sealed with SGS Numbered plastic wire seal



Drums sealed with SGS Numbered plastic wire seal



PHOTO REPORT

Page No.9 of 9

REF: BO2032221 -SK/A DATE: 07.07.2020

NOTE: This report reflects our findings at the time, date and place of Inspection only and does

not refer to any other matter.

CONCLUSION

On the basis of above we report that the "Quality, Quantity & Packing of the goods Loaded/ Delivered are strictly complying with specification of the goods indicated in relative proforma invoice and any amendment made there to presented to us by the buyer."

The above reflects our findings at the time, and place of inspection. This report does not relieve sellers/suppliers from their contractual responsibilities nor does it prejudice the buyers right of claim towards sellers / suppliers for compensation for any apparent and /or hidden defects not detected during our random inspection or occurring thereafter.

For SGS INDIA PRIVATE LIMITED

